

## TABLE OF CONTENTS

| Section                                                                                                                                   | Page |
|-------------------------------------------------------------------------------------------------------------------------------------------|------|
| Dedication                                                                                                                                | ii   |
| List of Tables                                                                                                                            | xxvi |
| List of Figures                                                                                                                           | xxix |
| Chapter I. Introduction                                                                                                                   | 1    |
| Chapter II. Course difficulty                                                                                                             | 7    |
| II.A. Discussion                                                                                                                          | 7    |
| II.B. Analysis                                                                                                                            | 9    |
| II.B.1. RDDF revision                                                                                                                     | 9    |
| II.B.1.a. 2004 QID RDDF                                                                                                                   | 10   |
| II.B.1.b. 2004 GCE RDDF                                                                                                                   | 10   |
| II.B.1.c. 2005 GCE RDDF                                                                                                                   | 11   |
| II.C. Results                                                                                                                             | 11   |
| II.C.1. Course length                                                                                                                     | 11   |
| II.C.1.a. Error in distance calculations                                                                                                  | 11   |
| II.C.1.a.i. Error in distance calculations based on the WGS84 Ellipsoid                                                                   | 11   |
| II.C.1.a.ii. Error in distance calculations based on slope                                                                                | 12   |
| II.C.1.a.iii. Error in distance calculations based on course smoothing                                                                    | 12   |
| II.C.1.b. Conformance to reported course lengths                                                                                          | 12   |
| II.C.2. Average course segment length                                                                                                     | 13   |
| II.C.3. The number of course segments for which the speed exceeds a reportable speed                                                      | 13   |
| II.C.4. The number of waypoints at which the change in bearing from one course segment to the next exceeds a reportable change in bearing | 15   |
| II.C.5. The minimum time required to complete the course at the maximum course segment speed allowed by the RDDF                          | 16   |
| II.C.6. The average time required to complete a course segment                                                                            | 17   |
| II.C.7. Evidence of course grooming                                                                                                       | 18   |
| II.C.7.a. "Taming"                                                                                                                        | 18   |
| II.C.7.b. Changes in observed slope from 2004 to 2005                                                                                     | 18   |
| II.C.7.c. Changes in maximum course segment length from 2004 to 2005                                                                      | 20   |
| II.C.7.d. Changes in lateral boundary offset from 2004 to 2005                                                                            | 21   |
| II.C.7.e. DARPA introduced forced deceleration lanes in 2005                                                                              | 21   |
| II.D. Conclusion                                                                                                                          | 22   |
| Chapter III. Vehicle Risk of Rollover                                                                                                     | 25   |
| III.A. Discussion                                                                                                                         | 25   |
| III.B. Analysis                                                                                                                           | 26   |
| III.B.1. Law of Sines approach                                                                                                            | 28   |
| III.B.2. Plane tangent to the ellipsoid approach                                                                                          | 28   |
| III.C. Results                                                                                                                            | 29   |
| III.C.1. Segment 2570-2571-2572                                                                                                           | 29   |
| III.D. Conclusion                                                                                                                         | 29   |

|              |                                                                                     |    |
|--------------|-------------------------------------------------------------------------------------|----|
| III.D.1.     | Effect of slope, friction, and suspension and tire effects                          | 31 |
| III.D.1.a.   | Effect of slope                                                                     | 31 |
| III.D.1.b.   | Effect of friction                                                                  | 32 |
| III.D.1.c.   | Suspension and tire effects                                                         | 33 |
| III.D.1.d.   | Safety factor                                                                       | 34 |
| III.D.2.     | Minimum design turn radius                                                          | 34 |
| III.D.3.     | Confirmation of forced deceleration lanes                                           | 35 |
| Chapter IV.  | Team evaluation of vehicle risk of rollover                                         | 36 |
| IV.A.        | Discussion                                                                          | 36 |
| IV.B.        | Analysis                                                                            | 36 |
| IV.C.        | Results                                                                             | 41 |
| IV.C.1.      | Mitigation of rollover risk                                                         | 41 |
| IV.C.2.      | Comparison of team strategies to mitigate rollover risk                             | 42 |
| IV.D.        | Conclusion                                                                          | 42 |
| Chapter V.   | Total Cost                                                                          | 44 |
| V.A.         | Discussion                                                                          | 44 |
| V.B.         | Analysis                                                                            | 47 |
| V.B.1.       | Comprehensive review of technical papers for 2004 QID and GCE participants          | 47 |
| V.B.2.       | Review of 2005 GCE technical papers                                                 | 47 |
| V.B.3.       | Classification of state sensors                                                     | 48 |
| V.B.3.a.     | Estimation of quantity of state sensors                                             | 48 |
| V.B.4.       | Classification of environment sensors                                               | 49 |
| V.B.4.a.     | Clarification of terminology                                                        | 50 |
| V.B.4.a.i.   | Laser range finders                                                                 | 50 |
| V.B.4.b.     | SICK LMS 291 LIDAR sensor model numbers                                             | 50 |
| V.B.5.       | Classification of navigation sensors                                                | 50 |
| V.B.5.a.     | Clarification of terminology                                                        | 51 |
| V.B.5.a.i.   | Geolocation                                                                         | 51 |
| V.B.5.a.ii.  | IMU and INS                                                                         | 51 |
| V.B.5.a.iii. | Speed                                                                               | 51 |
| V.B.5.b.     | Navigation sensors do not provide state information, and they are not state sensors | 51 |
| V.B.5.c.     | Estimation of quantity of navigation sensors                                        | 52 |
| V.B.6.       | Corrections and standardization                                                     | 53 |
| V.B.7.       | Elimination of state sensors from total cost                                        | 53 |
| V.B.8.       | Known, unknown, and estimated sensors                                               | 53 |
| V.C.         | Resolution of discrepancies in the published record                                 | 54 |
| V.C.1.       | Team 2004-01                                                                        | 54 |
| V.C.1.a.     | Unknown other sensors                                                               | 54 |
| V.C.1.b.     | Unknown cameras                                                                     | 55 |
| V.C.1.c.     | Unknown SICK LIDAR sensors                                                          | 55 |
| V.C.1.d.     | Unknown ultrasonic sensors                                                          | 55 |
| V.C.1.e.     | Unknown gyroscopes and unknown accelerometers                                       | 55 |

|          |                                                                        |    |
|----------|------------------------------------------------------------------------|----|
| V.C.1.f. | Unknown compass                                                        | 55 |
| V.C.1.g. | Trimble AgGPS 114                                                      | 56 |
| V.C.2.   | Team 2004-02                                                           | 56 |
| V.C.2.a. | Unknown state sensors                                                  | 56 |
| V.C.2.b. | OBD-II                                                                 | 56 |
| V.C.2.c. | Team 2004-02 MetalSense B1 touch sensors                               | 57 |
| V.C.2.d. | Point Grey Bumblebee cameras                                           | 57 |
| V.C.2.e. | FLIR A20M and unknown AVT camera                                       | 57 |
| V.C.2.f. | Epsilon Lambda ELSC71-1A                                               | 58 |
| V.C.2.g. | AGNC Land Navigator                                                    | 58 |
| V.C.3.   | Team 2004-03                                                           | 59 |
| V.C.3.a. | Unknown AOE's and unknown potentiometer                                | 59 |
| V.C.3.b. | Unknown Cognex cameras and unknown other camera                        | 60 |
| V.C.3.c. | Unknown DGPS receiver                                                  | 60 |
| V.C.3.d. | Unknown Crossbow gyroscopes                                            | 60 |
| V.C.3.e. | Unknown Crossbow IMU                                                   | 60 |
| V.C.4.   | Team 2004-04                                                           | 61 |
| V.C.4.a. | Honeywell ML500PS1PC pressure transducer                               | 61 |
| V.C.4.b. | Unknown Videre Design stereo camera pair                               | 61 |
| V.C.4.c. | Unknown other cameras                                                  | 62 |
| V.C.4.d. | Unknown PRECO RADAR and unknown long-range RADAR                       | 62 |
| V.C.4.e. | Unknown Garmin GPS receiver                                            | 62 |
| V.C.4.f. | Unknown NavCom GPS receiver                                            | 63 |
| V.C.4.g. | Unknown quadrature shaft encoder                                       | 63 |
| V.C.4.h. | Smiths Aerospace North Finding Module                                  | 63 |
| V.C.5.   | Team 2004-05                                                           | 63 |
| V.C.5.a. | Unknown state sensors                                                  | 64 |
| V.C.5.b. | Unknown SONAR sensors                                                  | 64 |
| V.C.5.c. | Unknown depth finders                                                  | 64 |
| V.C.5.d. | Unknown conductivity sensors                                           | 64 |
| V.C.5.e. | Unknown tactile sensors                                                | 64 |
| V.C.5.f. | Unknown SICK LIDAR sensors and trinocular camera system                | 65 |
| V.C.5.g. | Unknown Eaton RADAR                                                    | 65 |
| V.C.5.h. | Point Grey Bumblebee stereo camera pair                                | 66 |
| V.C.5.i. | Unknown navigation sensors                                             | 66 |
| V.C.5.j. | Unknown gyroscopes                                                     | 66 |
| V.C.5.k. | CSI Wireless Vector, CSI Wireless DGPS MAX, and unknown DGPS receivers | 66 |
| V.C.6.   | Team 2004-06                                                           | 67 |
| V.C.6.a. | Team 2004-06 stereo camera pair                                        | 67 |
| V.C.6.b. | Honeywell HMC1002                                                      | 68 |
| V.C.6.c. | NavCom SF-2050G                                                        | 68 |
| V.C.7.   | Team 2004-07                                                           | 68 |
| V.C.7.a. | Unknown potentiometer                                                  | 68 |

|           |                                                                         |    |
|-----------|-------------------------------------------------------------------------|----|
| V.C.7.b.  | Unknown ground whisker                                                  | 68 |
| V.C.7.c.  | Unknown SICK LIDAR sensor                                               | 69 |
| V.C.7.d.  | FLIR Omega                                                              | 69 |
| V.C.7.e.  | Unknown Rotomotion IMU and unknown Rotomotion magnetometer              | 69 |
| V.C.7.f.  | Unknown Hall Effect sensor                                              | 69 |
| V.C.8.    | Team 2004-08                                                            | 70 |
| V.C.8.a.  | Unknown optical sensor                                                  | 70 |
| V.C.8.b.  | Unknown ten-turn potentiometers                                         | 70 |
| V.C.8.c.  | Laseroptronix LDM 800-RS232 laser range finders                         | 71 |
| V.C.8.d.  | Unknown Applanix INS                                                    | 71 |
| V.C.9.    | Team 2004-09                                                            | 71 |
| V.C.9.a.  | Unknown state and navigation sensors                                    | 72 |
| V.C.9.b.  | Unknown gyroscope                                                       | 72 |
| V.C.9.c.  | Unknown vibration sensor                                                | 72 |
| V.C.9.d.  | Unknown SICK LIDAR sensor                                               | 72 |
| V.C.9.e.  | Unknown camera                                                          | 73 |
| V.C.9.f.  | MiTAC Navman TU60-D120 and MiTAC Ashtech DG16                           | 73 |
| V.C.10.   | Team 2004-10                                                            | 73 |
| V.C.10.a. | Unknown state sensors                                                   | 73 |
| V.C.10.b. | Riegl LMS-Q140i and unknown SICK LIDAR sensors                          | 74 |
| V.C.10.c. | Navtech DS2000                                                          | 74 |
| V.C.10.d. | Unknown SAIC stereo camera pair                                         | 74 |
| V.C.10.e. | Unknown other navigation sensors                                        | 75 |
| V.C.10.f. | Unknown Applanix sensor                                                 | 75 |
| V.C.11.   | Team 2004-11                                                            | 75 |
| V.C.11.a. | Unknown tachometer                                                      | 76 |
| V.C.11.b. | Unknown long-range laser ranger and unknown scanning laser range finder | 76 |
| V.C.11.c. | Unknown Omnivision sensor                                               | 76 |
| V.C.11.d. | MiTAC A12 and unknown CSI Wireless DGPS receiver                        | 76 |
| V.C.11.e. | Unknown other navigation sensors                                        | 76 |
| V.C.12.   | Team 2004-12                                                            | 77 |
| V.C.12.a. | Ultra Motion 2-B.125-DC426_12-4-P-/4-300                                | 77 |
| V.C.12.b. | Omron E2E-CR8B1 proximity sensors                                       | 77 |
| V.C.12.c. | Ultrasonic sensors                                                      | 77 |
| V.C.12.d. | SICK LMS 291-S05                                                        | 78 |
| V.C.13.   | Team 2004-13                                                            | 78 |
| V.C.13.a. | Unknown state sensors                                                   | 78 |
| V.C.13.b. | Unknown Hall Effect sensor and unknown absolute encoder                 | 78 |
| V.C.13.c. | Unknown compass                                                         | 79 |
| V.C.13.d. | Unknown camera                                                          | 79 |
| V.C.13.e. | Unknown SICK LIDAR sensors                                              | 79 |
| V.C.13.f. | Unknown Epsilon Lambda RADAR                                            | 80 |

|           |                                                        |    |
|-----------|--------------------------------------------------------|----|
| V.C.13.g. | Unknown ultrasonic sensors                             | 81 |
| V.C.13.h. | Unknown Rockwell Automation photoelectric sensors      | 81 |
| V.C.13.i. | Unknown accelerometer                                  | 81 |
| V.C.14.   | Team 2004-14                                           | 81 |
| V.C.14.a. | Unknown state sensors                                  | 81 |
| V.C.14.b. | Unknown Hall Effect sensor and unknown angular encoder | 82 |
| V.C.14.c. | Unknown magnetometer                                   | 82 |
| V.C.14.d. | Unknown cameras                                        | 82 |
| V.C.14.e. | Unknown SICK LIDAR sensors                             | 82 |
| V.C.14.f. | Unknown Epsilon Lambda RADAR                           | 83 |
| V.C.14.g. | Unknown ultrasonic sensors                             | 83 |
| V.C.14.h. | Unknown Rockwell Automation photoelectric sensors      | 83 |
| V.C.14.i. | Unknown tactile sensors                                | 84 |
| V.C.14.j. | Unknown accelerometer                                  | 84 |
| V.C.14.k. | Rockwell Collins GNP-10                                | 84 |
| V.C.15.   | Team 2004-15                                           | 84 |
| V.C.15.a. | Unknown state sensors                                  | 85 |
| V.C.15.b. | Polaroid 6500 SONAR sensors                            | 85 |
| V.C.15.c. | Unknown tactile sensors                                | 85 |
| V.C.15.d. | Unknown wheel encoders                                 | 85 |
| V.C.15.e. | Unknown accelerometer                                  | 86 |
| V.C.16.   | Team 2004-16                                           | 86 |
| V.C.16.a. | Unknown state sensors                                  | 86 |
| V.C.16.b. | Unknown compass                                        | 86 |
| V.C.16.c. | Unknown cameras                                        | 86 |
| V.C.16.d. | Unknown RADARs                                         | 87 |
| V.C.16.e. | Unknown SONAR sensors                                  | 87 |
| V.C.16.f. | Unknown SICK LIDAR sensors                             | 87 |
| V.C.16.g. | Unknown C&C Technologies C-Nav and unknown INS         | 88 |
| V.C.16.h. | Unknown solar sensors                                  | 88 |
| V.C.17.   | Team 2004-17                                           | 88 |
| V.C.17.a. | OBD-II                                                 | 89 |
| V.C.17.b. | Indigo Omega                                           | 89 |
| V.C.17.c. | Point Grey Dragonfly cameras                           | 89 |
| V.C.18.   | Team 2004-18                                           | 89 |
| V.C.18.a. | Unknown state sensors                                  | 90 |
| V.C.18.b. | Unknown compass                                        | 90 |
| V.C.18.c. | Unknown ISI INS                                        | 90 |
| V.C.18.d. | Unknown RADAR                                          | 91 |
| V.C.18.e. | NovAtel ProPak-LBplus                                  | 91 |
| V.C.18.f. | SICK LMS 220-30106                                     | 91 |
| V.C.18.g. | Unknown stereo camera pair                             | 92 |
| V.C.19.   | Team 2004-19                                           | 92 |
| V.C.19.a. | Unknown stereo camera pair                             | 92 |

|           |                                                       |     |
|-----------|-------------------------------------------------------|-----|
| V.C.19.b. | Unknown ultrasonic sensors                            | 93  |
| V.C.19.c. | Unknown Electro Switch OEs                            | 93  |
| V.C.19.d. | PNI Vector 2X                                         | 93  |
| V.C.20.   | Team 2004-20                                          | 93  |
| V.C.20.a. | Unknown state sensors                                 | 93  |
| V.C.20.b. | Eaton EVT-300                                         | 94  |
| V.C.20.c. | Unknown water sensors                                 | 94  |
| V.C.20.d. | Unknown ultrasonic sensors                            | 94  |
| V.C.20.e. | Unknown Crossbow INS                                  | 94  |
| V.C.20.f. | Unknown DICKY-john RADAR                              | 94  |
| V.C.20.g. | Unknown compass                                       | 95  |
| V.C.21.   | Team 2004-21                                          | 95  |
| V.C.21.a. | Unknown state sensors                                 | 95  |
| V.C.21.b. | Epsilon Lambda ELSC71-1A                              | 95  |
| V.C.21.c. | SensComp Developer's Kit                              | 95  |
| V.C.21.d. | Unknown IR sensors                                    | 96  |
| V.C.22.   | Team 2004-22                                          | 96  |
| V.C.22.a. | Unknown SpaceAge Control string potentiometers        | 96  |
| V.C.22.b. | Unknown temperature sensors                           | 96  |
| V.C.22.c. | Team 2004-22 Video System                             | 96  |
| V.C.22.d. | Unknown Microstrain gyroscope                         | 97  |
| V.C.22.e. | Unknown gyroscope                                     | 97  |
| V.C.22.f. | Unknown Honeywell pressure transducer                 | 97  |
| V.C.22.g. | Unknown u-blox GPS receiver                           | 97  |
| V.C.22.h. | Unknown Hall Effect sensors                           | 98  |
| V.C.23.   | Team 2004-23                                          | 98  |
| V.C.23.a. | Unknown state sensors                                 | 98  |
| V.C.23.b. | Unknown SICK LIDAR sensors                            | 98  |
| V.C.23.c. | Unknown Eaton RADARs                                  | 99  |
| V.C.23.d. | Unknown Massa ultrasonic sensors                      | 99  |
| V.C.23.e. | Unknown cameras                                       | 99  |
| V.C.23.f. | Unknown IMU                                           | 99  |
| V.C.23.g. | Unknown wheel speed sensors                           | 100 |
| V.C.24.   | Team 2004-24                                          | 100 |
| V.C.24.a. | Unknown pressure sensors                              | 100 |
| V.C.24.b. | Unknown power system sensors                          | 100 |
| V.C.24.c. | Unknown cameras                                       | 101 |
| V.C.24.d. | Unknown LIDAR sensor                                  | 101 |
| V.C.24.e. | Unknown Eaton RADAR                                   | 101 |
| V.C.24.f. | Unknown magnetometers, gyroscopes, and accelerometers | 102 |
| V.C.24.g. | Unknown NavCom GPS receiver                           | 102 |
| V.C.24.h. | Team 2004-24 wheel speed sensors                      | 102 |
| V.C.25.   | Team 2004-25                                          | 102 |

|           |                                                                                  |     |
|-----------|----------------------------------------------------------------------------------|-----|
| V.C.25.a. | Japan Servo DME 60B6HF, unknown linear potentiometer, and Bodine Electric 42A-5N | 103 |
| V.C.25.b. | Unknown state sensors                                                            | 103 |
| V.C.25.c. | Unknown thermal camera                                                           | 104 |
| V.C.25.d. | Unknown camera                                                                   | 104 |
| V.C.25.e. | Unknown SICK LIDAR sensors                                                       | 104 |
| V.C.25.f. | Unknown Eaton RADARs                                                             | 105 |
| V.C.25.g. | Unknown Honeywell INS                                                            | 105 |
| V.C.25.h. | Unknown wheel encoder                                                            | 105 |
| V.C.26.   | Team 2005-01                                                                     | 105 |
| V.C.26.a. | FLIR A20M and unknown AVT camera                                                 | 106 |
| V.C.26.b. | Unknown Eaton RADAR, Amphitech OASys, and unknown RADARs                         | 106 |
| V.C.26.c. | SICK LMS 211-30206 and unknown SICK LIDAR sensors                                | 107 |
| V.C.27.   | Team 2005-02                                                                     | 108 |
| V.C.27.a. | SICK LMS 291-S05 LIDAR sensors                                                   | 108 |
| V.C.27.b. | Unknown Eaton RADAR                                                              | 109 |
| V.C.27.c. | Unknown camera                                                                   | 109 |
| V.C.27.d. | Smiths Aerospace North Finding Module                                            | 109 |
| V.C.27.e. | Unknown NavCom GPS receiver                                                      | 110 |
| V.C.28.   | Team 2005-03                                                                     | 110 |
| V.C.28.a. | Proprietary LIDAR sensor                                                         | 110 |
| V.C.28.b. | NavCom SF-2050G and NovAtel ProPak-LBplus                                        | 111 |
| V.C.28.c. | Unknown IMU                                                                      | 111 |
| V.C.28.d. | Honeywell TALIN-4000                                                             | 111 |
| V.C.29.   | Team 2005-04                                                                     | 111 |
| V.C.29.a. | NovAtel ProPak-LBplus                                                            | 112 |
| V.C.29.b. | Unknown RADAR                                                                    | 112 |
| V.C.29.c. | Unknown stereo camera pair                                                       | 112 |
| V.C.29.d. | Unknown ultrasonic range finders                                                 | 112 |
| V.C.29.e. | Wheel speed sensors                                                              | 112 |
| V.C.30.   | Team 2005-05                                                                     | 113 |
| V.C.30.a. | Unknown SICK LIDAR sensors                                                       | 113 |
| V.C.30.b. | Mobileye ACP5                                                                    | 113 |
| V.C.30.c. | NovAtel ProPak-LBplus                                                            | 114 |
| V.C.30.d. | Systron Donner C-MIGITS III                                                      | 114 |
| V.C.30.e. | Unknown Hall Effect sensor                                                       | 114 |
| V.C.31.   | Team 2005-06                                                                     | 115 |
| V.C.31.a. | Oxford RT3000                                                                    | 115 |
| V.C.31.b. | Unknown stereo camera pair                                                       | 115 |
| V.C.31.c. | Riegl LMS-Q120 and unknown SICK LIDAR sensors                                    | 115 |
| V.C.31.d. | Unknown wheel speed sensor                                                       | 116 |
| V.C.32.   | Team 2005-07                                                                     | 116 |

|           |                                                                       |     |
|-----------|-----------------------------------------------------------------------|-----|
| V.C.32.a. | Unknown SICK LIDAR sensors, unknown GPS receiver, and unknown cameras | 116 |
| V.C.33.   | Team 2005-08                                                          | 117 |
| V.C.33.a. | SICK LMS 291-S14 and SICK LMS 211-30106                               | 117 |
| V.C.33.b. | Unknown ultrasonic sensors                                            | 118 |
| V.C.33.c. | Unknown Vansco RADAR                                                  | 118 |
| V.C.33.d. | Sony DFW-VL500 and unknown cameras                                    | 118 |
| V.C.33.e. | Unknown active bumper                                                 | 118 |
| V.C.34.   | Team 2005-09                                                          | 119 |
| V.C.34.a. | Unknown SICK LIDAR sensors                                            | 119 |
| V.C.34.b. | Unknown Eaton RADAR                                                   | 119 |
| V.C.34.c. | Unknown stereo camera pair and unknown machine vision system          | 120 |
| V.C.34.d. | Trimble AgGPS 132 DGPS receivers                                      | 120 |
| V.C.34.e. | Microbotics MIDG-II                                                   | 120 |
| V.C.34.f. | Unknown Honeywell compass                                             | 121 |
| V.C.34.g. | Unknown encoders                                                      | 121 |
| V.C.35.   | Team 2005-10                                                          | 121 |
| V.C.35.a. | Unknown SICK LIDAR sensors                                            | 121 |
| V.C.35.b. | Cognex DVT 542C cameras                                               | 122 |
| V.C.35.c. | Unknown stereo camera pair                                            | 122 |
| V.C.35.d. | NavCom SF-2050G                                                       | 122 |
| V.C.35.e. | Unknown Kearfott INS                                                  | 122 |
| V.C.35.f. | Unknown Crossbow accelerometer                                        | 123 |
| V.C.36.   | Team 2005-11                                                          | 123 |
| V.C.36.a. | Unknown SICK LIDAR sensors                                            | 123 |
| V.C.36.b. | Unknown Crossbow INS                                                  | 123 |
| V.C.36.c. | Unknown NovAtel GPS receiver                                          | 123 |
| V.C.36.d. | Unknown wheel speed sensors                                           | 124 |
| V.C.37.   | Team 2005-12                                                          | 124 |
| V.C.37.a. | Unknown Trimble DGPS receiver                                         | 124 |
| V.C.37.b. | Unknown CoPilot GPS receiver                                          | 124 |
| V.C.37.c. | Unknown encoder                                                       | 125 |
| V.C.37.d. | Unknown compass                                                       | 125 |
| V.C.38.   | Teams 2005-13 and 2005-14                                             | 125 |
| V.C.38.a. | Riegl LMS-Q140i and unknown SICK LIDAR sensors                        | 126 |
| V.C.38.b. | Navtech DS2000                                                        | 126 |
| V.C.38.c. | Unknown other sensors                                                 | 126 |
| V.C.38.d. | Unknown Applanix INS                                                  | 127 |
| V.C.38.e. | Trimble AgGPS 252                                                     | 128 |
| V.C.39.   | Team 2005-15                                                          | 128 |
| V.C.39.a. | Unknown SICK LIDAR sensors                                            | 128 |
| V.C.39.b. | Team 2005-15 stereo camera pair                                       | 129 |
| V.C.39.c. | Unknown ultrasonic sensors and unknown contact sensors                | 129 |
| V.C.39.d. | Unknown NavCom DGPS receiver                                          | 129 |

|            |                                                                          |     |
|------------|--------------------------------------------------------------------------|-----|
| V.C.39.e.  | Unknown Rockwell Collins IMU                                             | 130 |
| V.C.39.f.  | PNI TCM2 magnetometer                                                    | 130 |
| V.C.39.g.  | OEM speedometer encoder                                                  | 131 |
| V.C.40.    | Team 2005-16                                                             | 131 |
| V.C.40.a.  | Unknown GPS receiver and unknown GPS compass                             | 131 |
| V.C.40.b.  | Unknown IMU                                                              | 132 |
| V.C.40.c.  | Unknown SICK LIDAR sensors                                               | 132 |
| V.C.40.d.  | Unknown camera                                                           | 132 |
| V.C.40.e.  | Unknown Smart Microwave RADARs                                           | 133 |
| V.C.41.    | Team 2005-17                                                             | 133 |
| V.C.41.a.  | Unknown SICK LIDAR sensors                                               | 133 |
| V.C.41.b.  | Oxford RT3102                                                            | 133 |
| V.C.41.c.  | Unknown C&C Technologies C-Nav DGPS receiver                             | 134 |
| V.C.42.    | Team 2005-18                                                             | 134 |
| V.C.42.a.  | SICK LMS 221-30206, SICK LMS 291-S14, and SICK LMS 291-S05 LIDAR sensors | 134 |
| V.C.42.b.  | Point Grey Dragonfly stereo camera pairs                                 | 135 |
| V.C.42.c.  | Point Grey Dragonfly camera                                              | 135 |
| V.C.42.d.  | NovAtel DL-4plus and NavCom SF-2050G                                     | 135 |
| V.C.43.    | Team 2005-19                                                             | 136 |
| V.C.43.a.  | Unknown SICK LIDAR sensors                                               | 136 |
| V.C.43.b.  | Basler A311FC stereo camera pair                                         | 136 |
| V.C.43.c.  | Northrop Grumman LN-200                                                  | 136 |
| V.C.43.d.  | Trimble AgGPS 252                                                        | 137 |
| V.C.43.e.  | Unknown speed brake sensor                                               | 137 |
| V.C.44.    | Team 2005-20                                                             | 137 |
| V.C.44.a.  | Unknown LIDAR sensor(s)                                                  | 138 |
| V.C.44.b.  | Unknown RADAR(s)                                                         | 138 |
| V.C.44.c.  | Unknown stereo camera pair(s)                                            | 138 |
| V.C.44.d.  | NovAtel ProPak-LBplus and NovAtel HG1700 SPAN                            | 138 |
| V.C.45.    | Team 2005-21                                                             | 138 |
| V.C.45.a.  | Unknown SICK LIDAR sensors                                               | 138 |
| V.C.45.b.  | Unknown Ibeo LIDAR sensor                                                | 139 |
| V.C.45.c.  | Unknown cameras                                                          | 140 |
| V.C.45.d.  | Unknown wheel speed sensor and wheel angle sensor                        | 140 |
| V.C.46.    | Teams 2005-22 and 2005-23                                                | 141 |
| V.C.46.a.  | Unknown SICK LIDAR sensors                                               | 141 |
| V.C.46.b.  | NovAtel ProPak-LBplus and NovAtel HG1700 SPAN                            | 142 |
| V.C.46.c.  | Point Grey Bumblebee stereo camera pair                                  | 142 |
| V.C.46.d.  | Unknown encoders                                                         | 143 |
| V.D.       | Results                                                                  | 143 |
| V.D.1.     | 2004                                                                     | 143 |
| V.D.1.a.   | Known sensors by quantity (2004 QID and GCE participants)                | 143 |
| V.D.1.a.i. | State sensors                                                            | 143 |

|                |                                                                                |     |
|----------------|--------------------------------------------------------------------------------|-----|
| V.D.1.a.i.a.   | Known                                                                          | 143 |
| V.D.1.a.i.b.   | Unknown                                                                        | 144 |
| V.D.1.a.i.c.   | Estimated                                                                      | 144 |
| V.D.1.a.ii.    | Environment sensors                                                            | 144 |
| V.D.1.a.ii.a.  | Known                                                                          | 144 |
| V.D.1.a.ii.b.  | Unknown                                                                        | 144 |
| V.D.1.a.ii.c.  | Estimated                                                                      | 145 |
| V.D.1.a.iii.   | Navigation sensors                                                             | 145 |
| V.D.1.a.iii.a. | Known                                                                          | 145 |
| V.D.1.a.iii.b. | Unknown                                                                        | 145 |
| V.D.1.a.iii.c. | Estimated                                                                      | 145 |
| V.D.1.b.       | Known sensors by manufacturer (2004 QID and GCE participants)                  | 145 |
| V.D.1.b.i.     | State sensors                                                                  | 146 |
| V.D.1.b.i.a.   | Known                                                                          | 146 |
| V.D.1.b.i.b.   | Unknown                                                                        | 146 |
| V.D.1.b.ii.    | Environment sensors                                                            | 146 |
| V.D.1.b.ii.a.  | Known                                                                          | 146 |
| V.D.1.b.ii.b.  | Unknown                                                                        | 146 |
| V.D.1.b.iii.   | Navigation sensors                                                             | 147 |
| V.D.1.b.iii.a. | Known                                                                          | 147 |
| V.D.1.b.iii.b. | Unknown                                                                        | 147 |
| V.D.1.c.       | Known sensors by manufacturer and model number (2004 QID and GCE participants) | 147 |
| V.D.1.c.i.     | State sensors                                                                  | 147 |
| V.D.1.c.i.a.   | Known                                                                          | 147 |
| V.D.1.c.i.b.   | Unknown                                                                        | 148 |
| V.D.1.c.ii.    | Environment sensors                                                            | 148 |
| V.D.1.c.ii.a.  | Known                                                                          | 148 |
| V.D.1.c.ii.b.  | Unknown                                                                        | 148 |
| V.D.1.c.iii.   | Navigation sensors                                                             | 148 |
| V.D.1.c.iii.a. | Known                                                                          | 149 |
| V.D.1.c.iii.b. | Unknown                                                                        | 149 |
| V.D.2.         | 2005                                                                           | 149 |
| V.D.2.a.       | Known sensors by quantity (2005 GCE participants)                              | 149 |
| V.D.2.a.i.     | Environment sensors                                                            | 149 |
| V.D.2.a.i.a.   | Known                                                                          | 149 |
| V.D.2.a.i.b.   | Unknown                                                                        | 149 |
| V.D.2.a.ii.    | Navigation sensors                                                             | 149 |
| V.D.2.a.ii.a.  | Known                                                                          | 150 |
| V.D.2.a.ii.b.  | Unknown                                                                        | 150 |
| V.D.2.a.ii.c.  | Estimated                                                                      | 150 |
| V.D.2.b.       | Known sensors by manufacturer (2005 GCE participants)                          | 150 |
| V.D.2.b.i.     | Environment sensors                                                            | 150 |
| V.D.2.b.i.a.   | Known                                                                          | 150 |

|               |                                                                                             |     |
|---------------|---------------------------------------------------------------------------------------------|-----|
| V.D.2.b.i.b.  | Unknown                                                                                     | 150 |
| V.D.2.b.ii.   | Navigation sensors                                                                          | 150 |
| V.D.2.b.ii.a. | Known                                                                                       | 150 |
| V.D.2.b.ii.b. | Unknown                                                                                     | 150 |
| V.D.2.c.      | Known sensors by manufacturer and model number (2005 GCE participants)                      | 151 |
| V.D.2.c.i.    | Environment sensors                                                                         | 151 |
| V.D.2.c.i.a.  | Known                                                                                       | 151 |
| V.D.2.c.i.b.  | Unknown                                                                                     | 151 |
| V.D.2.c.ii.   | Navigation sensors                                                                          | 151 |
| V.D.2.c.ii.a. | Known                                                                                       | 151 |
| V.D.2.c.ii.b. | Unknown                                                                                     | 151 |
| V.D.3.        | Summary of results                                                                          | 151 |
| V.D.3.a.      | Differences between 2004 QID and GCE results                                                | 152 |
| V.D.3.b.      | Differences between 2004 and 2005 GCE results                                               | 152 |
| V.E.          | Conclusion                                                                                  | 153 |
| V.E.1.        | Primary sources of uncertainty                                                              | 153 |
| V.E.1.a.      | Technical paper requirements                                                                | 153 |
| V.E.1.b.      | Errors, omissions, and inconsistencies                                                      | 155 |
| V.E.1.c.      | Insufficient technical detail                                                               | 155 |
| V.E.1.d.      | Poor revision control                                                                       | 158 |
| V.E.2.        | Additional sources of uncertainty                                                           | 158 |
| V.E.2.a.      | The cost of labor was not reported                                                          | 160 |
| V.E.2.b.      | Labor cost estimation                                                                       | 161 |
| V.E.2.c.      | Estimation of comparative costs                                                             | 163 |
| V.E.2.d.      | The cost of sensors was not reported                                                        | 163 |
| V.E.2.d.i.    | Pricing information for most high-quality sensors is not available from published records   | 164 |
| V.E.2.d.ii.   | Insufficient technical detail was reported to determine the total cost of reported sensors  | 165 |
| V.E.2.d.iii.  | Some teams referred to sensors to describe “systems” or reported the “system” as the sensor | 166 |
| V.E.2.e.      | The cost of equipment donated or loaned to the teams was not reported                       | 166 |
| V.E.2.e.i.    | The cost of computing resources was not reported                                            | 167 |
| V.E.2.f.      | Confidential and proprietary appendixes conceal technical detail                            | 167 |
| V.E.2.g.      | Anecdotal evidence                                                                          | 170 |
| Chapter VI.   | High-quality obstacle and path detection sensors                                            | 173 |
| VI.A.         | Discussion                                                                                  | 173 |
| VI.B.         | Analysis                                                                                    | 173 |
| VI.B.1.       | VISION sensors                                                                              | 173 |
| VI.B.1.a.     | Stereo camera pair                                                                          | 173 |
| VI.B.1.a.i.   | High-quality stereo camera pairs                                                            | 173 |
| VI.B.1.a.ii.  | Other stereo camera pairs                                                                   | 175 |

|               |                                                                                                                                                                 |     |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|
| VI.B.1.b.     | Other cameras                                                                                                                                                   | 176 |
| VI.B.2.       | RADAR sensors                                                                                                                                                   | 176 |
| VI.B.2.a.     | Navigation RADAR                                                                                                                                                | 176 |
| VI.B.2.b.     | Other RADAR                                                                                                                                                     | 178 |
| VI.B.3.       | LIDAR sensors                                                                                                                                                   | 179 |
| VI.B.3.a.     | Scanning laser range finders                                                                                                                                    | 180 |
| VI.B.3.b.     | Other LIDAR                                                                                                                                                     | 181 |
| VI.C.         | Results                                                                                                                                                         | 181 |
| VI.C.1.       | Differences in the number of teams using high-quality sensors from 2004 to 2005                                                                                 | 181 |
| VI.C.2.       | Differences in the number of high-quality sensors in use                                                                                                        | 182 |
| VI.D.         | Conclusions                                                                                                                                                     | 182 |
| VI.D.1.       | Reduce the number of obstacle and path detection sensors in use by eliminating other sensors                                                                    | 182 |
| VI.D.2.       | Use high-quality sensors which provide a point-map of the environment                                                                                           | 183 |
| VI.D.3.       | Use LIDAR sensors with capabilities similar to the SICK LMS 291 product family                                                                                  | 185 |
| Chapter VII.  | Navigation sensor integration                                                                                                                                   | 186 |
| VII.A.        | Discussion                                                                                                                                                      | 186 |
| VII.B.        | Analysis                                                                                                                                                        | 186 |
| VII.C.        | Results                                                                                                                                                         | 196 |
| VII.C.1.      | Differences in the number of teams utilizing a COTS component to integrate navigation sensors from 2004 to 2005                                                 | 196 |
| VII.C.2.      | Differences in the number of teams utilizing a COTS component which implemented a Kalman filter or independently implementing a Kalman filter from 2004 to 2005 | 197 |
| VII.C.3.      | Differences in the number of teams utilizing a COTS component which implemented a Kalman filter from 2004 to 2005                                               | 197 |
| VII.D.        | Conclusions                                                                                                                                                     | 198 |
| VII.D.1.      | Use a COTS component to integrate navigation sensors                                                                                                            | 198 |
| VII.D.2.      | Use a Kalman filter to integrate navigation sensors                                                                                                             | 199 |
| Chapter VIII. | Sensor Limitations                                                                                                                                              | 201 |
| VIII.A.       | Discussion                                                                                                                                                      | 201 |
| VIII.A.1.     | Calculation of stopping distance                                                                                                                                | 201 |
| VIII.A.2.     | Calculation of field-of-view limitations                                                                                                                        | 202 |
| VIII.A.2.a.   | Sensors with a field-of-view greater than or equal to 40 degrees would have been able to reliably detect obstacles in every turn of the 2004 and 2005 GCE       | 203 |
| VIII.A.2.b.   | Eaton EVT-300 field-of-view considerations                                                                                                                      | 204 |
| VIII.A.3.     | Maximum effective range for various sensors                                                                                                                     | 204 |
| VIII.A.4.     | Definition of maximum obstacle detection range                                                                                                                  | 205 |
| VIII.A.4.a.   | The maximum obstacle detection range for LIDAR sensors is limited by reflectivity                                                                               | 205 |

|                 |                                                                                                     |     |
|-----------------|-----------------------------------------------------------------------------------------------------|-----|
| VIII.A.4.b.     | Several teams overstated or overestimated the maximum effective range of sensors in use by the team | 206 |
| VIII.A.4.c.     | Eaton RADAR sensor maximum obstacle detection range considerations                                  | 208 |
| VIII.B.         | Analysis                                                                                            | 208 |
| VIII.B.1.       | Team 2004-01                                                                                        | 208 |
| VIII.B.1.a.     | Stopping distance                                                                                   | 208 |
| VIII.B.1.a.i.   | Unknown cameras                                                                                     | 209 |
| VIII.B.1.a.ii.  | Unknown SICK LIDAR sensors                                                                          | 210 |
| VIII.B.1.b.     | Field-of-view limitations                                                                           | 210 |
| VIII.B.2.       | Team 2004-02                                                                                        | 210 |
| VIII.B.2.a.     | Stopping distance                                                                                   | 210 |
| VIII.B.2.a.i.   | SICK LMS 211-30206                                                                                  | 210 |
| VIII.B.2.a.ii.  | Point Grey Bumblebee stereo camera pairs, FLIR A20M, and unknown AVT camera                         | 211 |
| VIII.B.2.a.iii. | Epsilon Lambda ELSC71-1A                                                                            | 211 |
| VIII.B.2.b.     | Field-of-view limitations                                                                           | 211 |
| VIII.B.2.b.i.   | Epsilon Lambda ELSC71-1A                                                                            | 211 |
| VIII.B.2.b.ii.  | Point Grey Bumblebee stereo camera pairs, FLIR A20M, and unknown AVT camera                         | 212 |
| VIII.B.3.       | Team 2004-03                                                                                        | 212 |
| VIII.B.3.a.     | Stopping distance                                                                                   | 212 |
| VIII.B.3.a.i.   | Unknown Cognex cameras and unknown camera                                                           | 212 |
| VIII.B.3.a.ii.  | Epsilon Lambda ELSC71-1A                                                                            | 213 |
| VIII.B.3.b.     | Field-of-view limitations                                                                           | 213 |
| VIII.B.3.b.i.   | Unknown Cognex cameras and unknown camera                                                           | 213 |
| VIII.B.3.b.ii.  | Epsilon Lambda ELSC71-1A                                                                            | 213 |
| VIII.B.4.       | Team 2004-04                                                                                        | 214 |
| VIII.B.4.a.     | Stopping distance                                                                                   | 214 |
| VIII.B.4.a.i.   | Unknown Videre Design stereo camera pair and unknown cameras                                        | 214 |
| VIII.B.4.a.ii.  | Unknown long-range RADAR                                                                            | 214 |
| VIII.B.4.a.iii. | SICK LMS 200-30106                                                                                  | 214 |
| VIII.B.4.b.     | Field-of-view limitations                                                                           | 215 |
| VIII.B.4.b.i.   | Unknown Videre Design stereo camera pair and unknown cameras                                        | 215 |
| VIII.B.4.b.ii.  | Unknown long-range RADAR                                                                            | 215 |
| VIII.B.5.       | Team 2004-05                                                                                        | 215 |
| VIII.B.5.a.     | Stopping distance                                                                                   | 215 |
| VIII.B.5.a.i.   | Unknown SICK LIDAR sensors                                                                          | 215 |
| VIII.B.5.a.ii.  | Unknown Eaton RADAR                                                                                 | 216 |
| VIII.B.5.a.iii. | Point Grey Bumblebee stereo camera pair                                                             | 216 |
| VIII.B.5.b.     | Field-of-view limitations                                                                           | 216 |
| VIII.B.5.b.i.   | Unknown Eaton RADAR                                                                                 | 216 |

|                  |                                           |     |
|------------------|-------------------------------------------|-----|
| VIII.B.5.b.ii.   | Point Grey Bumblebee stereo camera pair   | 216 |
| VIII.B.6.        | Team 2004-06                              | 217 |
| VIII.B.6.a.      | Stopping distance                         | 218 |
| VIII.B.6.b.      | Field-of-view limitations                 | 218 |
| VIII.B.7.        | Team 2004-07                              | 218 |
| VIII.B.7.a.      | Stopping distance                         | 218 |
| VIII.B.7.a.i.    | Unknown SICK LIDAR sensor                 | 218 |
| VIII.B.7.a.ii.   | Epsilon Lambda ELSC71-1A                  | 219 |
| VIII.B.7.a.iii.  | FLIR Omega and Sony DFW-VL500 cameras     | 219 |
| VIII.B.7.b.      | Field-of-view limitations                 | 219 |
| VIII.B.7.b.i.    | Epsilon Lambda ELSC71-1A                  | 219 |
| VIII.B.7.b.ii.   | FLIR Omega and Sony DFW-VL500 cameras     | 220 |
| VIII.B.8.        | Team 2004-08                              | 220 |
| VIII.B.8.a.      | Stopping distance                         | 220 |
| VIII.B.8.a.i.    | Laseroptronix LDM 800-RS232 LIDAR sensors | 220 |
| VIII.B.8.a.ii.   | Laseroptronix Sea-Lynx                    | 221 |
| VIII.B.8.a.iii.  | Cohu 1330 cameras                         | 221 |
| VIII.B.8.b.      | Field-of-view limitations                 | 221 |
| VIII.B.8.b.i.    | Laseroptronix LDM 800-RS232 LIDAR sensors | 221 |
| VIII.B.8.b.ii.   | Laseroptronix Sea-Lynx                    | 221 |
| VIII.B.8.b.iii.  | Cohu 1330 cameras                         | 222 |
| VIII.B.9.        | Team 2004-09                              | 222 |
| VIII.B.9.a.      | Stopping distance                         | 222 |
| VIII.B.9.a.i.    | Unknown SICK LIDAR sensor                 | 222 |
| VIII.B.9.a.ii.   | Unknown camera                            | 223 |
| VIII.B.9.b.      | Field-of-view limitations                 | 223 |
| VIII.B.10.       | Team 2004-10                              | 223 |
| VIII.B.10.a.     | Stopping distance                         | 223 |
| VIII.B.10.a.i.   | Unknown SICK LIDAR sensors                | 223 |
| VIII.B.10.a.ii.  | Riegl LMS-Q140i                           | 224 |
| VIII.B.10.b.     | Field-of-view limitations                 | 224 |
| VIII.B.11.       | Team 2004-11                              | 224 |
| VIII.B.11.a.     | Stopping distance                         | 224 |
| VIII.B.11.a.i.   | Unknown long-range laser ranger           | 224 |
| VIII.B.11.a.ii.  | Unknown scanning laser range finder       | 225 |
| VIII.B.11.a.iii. | Unknown Omnivision sensor                 | 225 |
| VIII.B.11.b.     | Field-of-view limitations                 | 225 |
| VIII.B.11.b.i.   | Unknown long-range laser ranger           | 225 |
| VIII.B.11.b.ii.  | Unknown Omnivision sensor                 | 225 |
| VIII.B.12.       | Team 2004-12                              | 225 |
| VIII.B.12.a.     | Stopping distance                         | 226 |
| VIII.B.13.       | Team 2004-13                              | 226 |
| VIII.B.13.a.     | Stopping distance                         | 226 |
| VIII.B.13.a.i.   | Unknown SICK LIDAR sensors                | 226 |

|                  |                                         |     |
|------------------|-----------------------------------------|-----|
| VIII.B.13.a.ii.  | Unknown camera                          | 226 |
| VIII.B.13.a.iii. | Unknown Epsilon Lambda RADAR            | 227 |
| VIII.B.13.b.     | Field-of-view limitations               | 227 |
| VIII.B.13.b.i.   | Unknown camera                          | 227 |
| VIII.B.13.b.ii.  | Unknown Epsilon Lambda RADAR            | 227 |
| VIII.B.14.       | Team 2004-14                            | 228 |
| VIII.B.14.a.     | Stopping distance                       | 228 |
| VIII.B.14.a.i.   | Unknown cameras                         | 228 |
| VIII.B.14.a.ii.  | Unknown SICK LIDAR sensors              | 228 |
| VIII.B.14.a.iii. | Unknown Epsilon Lambda RADAR            | 229 |
| VIII.B.14.b.     | Field-of-view limitations               | 229 |
| VIII.B.14.b.i.   | Unknown cameras                         | 229 |
| VIII.B.14.b.ii.  | Unknown Epsilon Lambda RADAR            | 229 |
| VIII.B.15.       | Team 2004-15                            | 230 |
| VIII.B.15.a.     | Stopping distance                       | 230 |
| VIII.B.15.b.     | SICK LMS 211-30206                      | 230 |
| VIII.B.15.c.     | Eaton EVT-300                           | 231 |
| VIII.B.15.c.i.   | Field-of-view limitations               | 231 |
| VIII.B.16.       | Team 2004-16                            | 231 |
| VIII.B.16.a.     | Stopping distance                       | 231 |
| VIII.B.16.a.i.   | Unknown cameras                         | 232 |
| VIII.B.16.a.ii.  | Unknown RADAR                           | 232 |
| VIII.B.16.b.     | Unknown SICK LIDAR sensors              | 232 |
| VIII.B.16.c.     | Field-of-view limitations               | 232 |
| VIII.B.17.       | Team 2004-17                            | 232 |
| VIII.B.17.a.     | Stopping distance                       | 233 |
| VIII.B.17.a.i.   | Point Grey Dragonfly stereo camera pair | 233 |
| VIII.B.17.a.ii.  | SICK LMS 221-30206                      | 233 |
| VIII.B.17.b.     | Field-of-view limitations               | 233 |
| VIII.B.18.       | Team 2004-18                            | 233 |
| VIII.B.18.a.     | Stopping distance                       | 234 |
| VIII.B.18.a.i.   | Unknown RADARs                          | 234 |
| VIII.B.18.a.ii.  | SICK LMS 220-30106                      | 234 |
| VIII.B.18.a.iii. | Unknown stereo camera pair              | 234 |
| VIII.B.18.b.     | Field-of-view limitations               | 235 |
| VIII.B.18.b.i.   | Unknown RADARs                          | 235 |
| VIII.B.18.b.ii.  | Unknown stereo camera pair              | 235 |
| VIII.B.19.       | Team 2004-19                            | 235 |
| VIII.B.19.a.     | Stopping distance                       | 235 |
| VIII.B.19.a.i.   | Unknown stereo camera pair              | 236 |
| VIII.B.19.a.ii.  | SICK DME 2000                           | 236 |
| VIII.B.19.b.     | Field-of-view limitations               | 236 |
| VIII.B.19.b.i.   | Unknown stereo camera pair              | 236 |
| VIII.B.19.b.ii.  | SICK DME 2000                           | 236 |

|                                                                                               |     |
|-----------------------------------------------------------------------------------------------|-----|
| VIII.B.20. Team 2004-20                                                                       | 236 |
| VIII.B.20.a. Stopping distance                                                                | 237 |
| VIII.B.20.a.i. SICK LMS 221-30206                                                             | 237 |
| VIII.B.20.a.ii. Eaton EVT-300                                                                 | 237 |
| VIII.B.20.a.iii. Unibrain Fire-i 400                                                          | 238 |
| VIII.B.20.b. Field-of-view limitations                                                        | 238 |
| VIII.B.20.b.i. Eaton EVT-300                                                                  | 238 |
| VIII.B.20.b.ii. Unibrain Fire-i 400                                                           | 238 |
| VIII.B.21. Team 2004-21                                                                       | 238 |
| VIII.B.21.a. Stopping distance                                                                | 239 |
| VIII.B.21.b. Field-of-view limitations                                                        | 239 |
| VIII.B.22. Team 2004-22                                                                       | 240 |
| VIII.B.22.a. Stopping distance                                                                | 240 |
| VIII.B.22.b. Field-of-view limitations                                                        | 240 |
| VIII.B.23. Team 2004-23                                                                       | 240 |
| VIII.B.23.a. Stopping distance                                                                | 241 |
| VIII.B.23.a.i. Unknown SICK LIDAR sensors                                                     | 241 |
| VIII.B.23.a.ii. Unknown Eaton RADARs                                                          | 241 |
| VIII.B.23.a.iii. Unknown cameras                                                              | 242 |
| VIII.B.23.b. Field-of-view limitations                                                        | 242 |
| VIII.B.23.b.i. Unknown Eaton RADARs                                                           | 242 |
| VIII.B.23.b.ii. Unknown cameras                                                               | 243 |
| VIII.B.24. Team 2004-24                                                                       | 243 |
| VIII.B.24.a. Stopping distance                                                                | 243 |
| VIII.B.24.a.i. Unknown cameras                                                                | 243 |
| VIII.B.24.a.ii. Unknown LIDAR sensor                                                          | 243 |
| VIII.B.24.a.iii. Unknown Eaton RADAR                                                          | 243 |
| VIII.B.24.b. Field-of-view limitations                                                        | 244 |
| VIII.B.24.b.i. Unknown cameras                                                                | 244 |
| VIII.B.24.b.ii. Unknown Eaton RADAR                                                           | 244 |
| VIII.B.25. Team 2004-25                                                                       | 244 |
| VIII.B.25.a. Stopping distance                                                                | 244 |
| VIII.B.25.b. Unknown camera                                                                   | 245 |
| VIII.B.25.b.i. Unknown SICK LIDAR sensors                                                     | 245 |
| VIII.B.25.b.ii. Unknown Eaton RADARs                                                          | 245 |
| VIII.B.25.c. Field-of-view limitations                                                        | 245 |
| VIII.B.25.c.i. Unknown camera                                                                 | 245 |
| VIII.B.25.c.ii. Unknown Eaton RADARs                                                          | 245 |
| VIII.B.26. Team 2005-01                                                                       | 246 |
| VIII.B.26.a. Stopping distance                                                                | 246 |
| VIII.B.26.a.i. Unknown AVT camera, FLIR A20M, and Point Grey<br>Bumblebee stereo camera pairs | 246 |
| VIII.B.26.a.ii. Unknown Eaton RADAR and unknown RADAR                                         | 247 |
| VIII.B.26.a.iii. Amphitech OASys                                                              | 247 |

|                  |                                                       |     |
|------------------|-------------------------------------------------------|-----|
| VIII.B.26.a.iv.  | SICK LMS 211-30206 and unknown SICK LIDAR sensors     | 247 |
| VIII.B.26.b.     | Field-of-view limitations                             | 247 |
| VIII.B.27.       | Team 2005-02                                          | 248 |
| VIII.B.27.a.     | Stopping distance                                     | 248 |
| VIII.B.27.a.i.   | SICK LMS 291-S05 LIDAR sensors                        | 248 |
| VIII.B.27.a.ii.  | Unknown camera                                        | 248 |
| VIII.B.27.b.     | Field-of-view limitations                             | 249 |
| VIII.B.28.       | Team 2005-03                                          | 249 |
| VIII.B.28.a.     | Stopping distance                                     | 249 |
| VIII.B.28.b.     | Field-of-view limitations                             | 249 |
| VIII.B.29.       | Team 2005-04                                          | 249 |
| VIII.B.29.a.     | Stopping distance                                     | 249 |
| VIII.B.29.a.i.   | SICK LMS 221-30206 LIDAR sensors                      | 249 |
| VIII.B.29.a.ii.  | Eaton EVT-300                                         | 250 |
| VIII.B.29.a.iii. | Proprietary RADAR                                     | 250 |
| VIII.B.29.a.iv.  | Unknown stereo camera pair                            | 250 |
| VIII.B.29.b.     | Field-of-view limitations                             | 251 |
| VIII.B.29.b.i.   | Proprietary RADAR and unknown stereo camera pair      | 251 |
| VIII.B.29.b.ii.  | Eaton EVT-300                                         | 251 |
| VIII.B.30.       | Team 2005-05                                          | 251 |
| VIII.B.30.a.     | Stopping distance                                     | 252 |
| VIII.B.30.a.i.   | Unknown SICK LIDAR sensors                            | 252 |
| VIII.B.30.a.ii.  | Mobileye ACP5                                         | 252 |
| VIII.B.30.b.     | Field-of-view limitations                             | 252 |
| VIII.B.30.b.i.   | Unknown SICK LIDAR sensor                             | 252 |
| VIII.B.30.b.ii.  | Mobileye ACP5                                         | 252 |
| VIII.B.31.       | Team 2005-06                                          | 253 |
| VIII.B.31.a.     | Stopping distance                                     | 253 |
| VIII.B.31.b.     | Field-of-view limitations                             | 253 |
| VIII.B.32.       | Team 2005-07                                          | 254 |
| VIII.B.32.a.     | Stopping distance                                     | 254 |
| VIII.B.32.a.i.   | Unknown SICK LIDAR sensors                            | 254 |
| VIII.B.32.a.ii.  | Unknown stereo camera pairs                           | 254 |
| VIII.B.33.       | Team 2005-08                                          | 255 |
| VIII.B.33.a.     | Stopping distance                                     | 255 |
| VIII.B.33.a.i.   | Riegl LMS-Q120 LIDAR sensors                          | 255 |
| VIII.B.33.a.ii.  | SICK LMS 291-S14 and 211-30106 LIDAR sensors          | 255 |
| VIII.B.33.a.iii. | Delphi Forewarn ACC3 RADARs                           | 255 |
| VIII.B.33.a.iv.  | Sony DFW-VL500 stereo camera pair and unknown cameras | 256 |
| VIII.B.33.b.     | Field-of-view limitations                             | 256 |
| VIII.B.34.       | Team 2005-09                                          | 256 |
| VIII.B.34.a.     | Stopping distance                                     | 256 |
| VIII.B.35.       | Team 2005-10                                          | 256 |
| VIII.B.35.a.     | Stopping distance                                     | 257 |

|                  |                                                        |     |
|------------------|--------------------------------------------------------|-----|
| VIII.B.35.a.i.   | Unknown SICK LIDAR sensors                             | 257 |
| VIII.B.35.a.ii.  | Cognex DVT 542C cameras                                | 257 |
| VIII.B.35.a.iii. | Unknown stereo camera pair                             | 257 |
| VIII.B.35.a.iv.  | Optech ILRIS-3D                                        | 257 |
| VIII.B.35.b.     | Field-of-view limitations                              | 258 |
| VIII.B.35.b.i.   | Cognex DVT 542C cameras                                | 258 |
| VIII.B.35.b.ii.  | Unknown stereo camera pair                             | 258 |
| VIII.B.35.b.iii. | Optech ILRIS-3D                                        | 258 |
| VIII.B.36.       | Team 2005-11                                           | 258 |
| VIII.B.36.a.     | Stopping distance                                      | 258 |
| VIII.B.37.       | Team 2005-12                                           | 259 |
| VIII.B.37.a.     | Stopping distance                                      | 259 |
| VIII.B.37.b.     | Field-of-view limitations                              | 259 |
| VIII.B.38.       | Teams 2005-13 and 2005-14                              | 259 |
| VIII.B.38.a.     | Stopping distance                                      | 259 |
| VIII.B.38.a.i.   | Riegl LMS-Q140i                                        | 260 |
| VIII.B.38.a.ii.  | Unknown SICK LIDAR sensors                             | 260 |
| VIII.B.38.a.iii. | Navtech DS2000                                         | 260 |
| VIII.B.38.b.     | Field-of-view limitations                              | 260 |
| VIII.B.38.b.i.   | Riegl LMS-Q140i                                        | 260 |
| VIII.B.38.b.ii.  | Navtech DS2000 RADAR                                   | 261 |
| VIII.B.39.       | Team 2005-15                                           | 261 |
| VIII.B.39.a.     | Stopping distance                                      | 261 |
| VIII.B.39.a.i.   | Unknown SICK LIDAR sensors                             | 261 |
| VIII.B.39.a.ii.  | Proprietary stereo camera pair                         | 261 |
| VIII.B.39.b.     | Field-of-view limitations                              | 262 |
| VIII.B.39.b.i.   | Proprietary stereo camera pair                         | 262 |
| VIII.B.40.       | Team 2005-16                                           | 262 |
| VIII.B.40.a.     | Stopping distance                                      | 262 |
| VIII.B.40.a.i.   | Unknown SICK LIDAR sensors                             | 262 |
| VIII.B.40.a.ii.  | Unknown camera                                         | 262 |
| VIII.B.40.b.     | Field-of-view limitations                              | 262 |
| VIII.B.40.b.i.   | Unknown camera                                         | 262 |
| VIII.B.41.       | Team 2005-17                                           | 263 |
| VIII.B.41.a.     | Stopping distance                                      | 263 |
| VIII.B.42.       | Team 2005-18                                           | 263 |
| VIII.B.42.a.     | Stopping distance                                      | 263 |
| VIII.B.42.a.i.   | SICK LMS 221-30206, 291-S14, and 291-S05 LIDAR sensors | 263 |
| VIII.B.42.a.ii.  | Riegl LMS-Q120i                                        | 264 |
| VIII.B.42.a.iii. | Point Grey Dragonfly cameras                           | 264 |
| VIII.B.42.b.     | Field-of-view limitations                              | 264 |
| VIII.B.43.       | Team 2005-19                                           | 264 |
| VIII.B.43.a.     | Stopping distance                                      | 265 |
| VIII.B.44.       | Team 2005-20                                           | 265 |

|                  |                                                              |     |
|------------------|--------------------------------------------------------------|-----|
| VIII.B.44.a.     | Stopping distance                                            | 265 |
| VIII.B.44.a.i.   | Unknown LIDAR sensor(s)                                      | 265 |
| VIII.B.44.a.ii.  | Unknown RADAR(s)                                             | 266 |
| VIII.B.44.a.iii. | Unknown stereo camera pair(s)                                | 266 |
| VIII.B.44.b.     | Field-of-view limitations                                    | 266 |
| VIII.B.44.b.i.   | Unknown RADAR(s)                                             | 266 |
| VIII.B.44.b.ii.  | Unknown stereo camera pair(s)                                | 267 |
| VIII.B.45.       | Team 2005-21                                                 | 267 |
| VIII.B.45.a.     | Stopping distance                                            | 267 |
| VIII.B.45.a.i.   | Unknown SICK LIDAR sensors                                   | 267 |
| VIII.B.45.a.ii.  | Unknown Ibeo LIDAR sensor                                    | 267 |
| VIII.B.45.a.iii. | Unknown cameras                                              | 268 |
| VIII.B.45.b.     | Field-of-view limitations                                    | 268 |
| VIII.B.45.b.i.   | Unknown Ibeo LIDAR sensor                                    | 268 |
| VIII.B.45.b.ii.  | Unknown cameras                                              | 268 |
| VIII.B.46.       | Team 2005-22                                                 | 268 |
| VIII.B.46.a.     | Stopping distance                                            | 268 |
| VIII.B.46.a.i.   | Unknown SICK LIDAR sensor                                    | 268 |
| VIII.B.46.a.ii.  | Point Grey Bumblebee stereo camera pair                      | 269 |
| VIII.B.46.b.     | Field-of-view limitations                                    | 269 |
| VIII.B.47.       | Team 2005-23                                                 | 269 |
| VIII.B.47.a.     | Stopping distance                                            | 269 |
| VIII.B.47.a.i.   | Unknown SICK LIDAR sensors                                   | 269 |
| VIII.B.47.a.ii.  | Point Grey Bumblebee stereo camera pair                      | 269 |
| VIII.B.47.b.     | Field-of-view limitations                                    | 270 |
| VIII.C.          | Results                                                      | 270 |
| VIII.C.1.        | 2004                                                         | 270 |
| VIII.C.2.        | 2005                                                         | 272 |
| VIII.C.3.        | Comparison of 2004 results to 2005 results                   | 274 |
| VIII.C.4.        | Effect of the representative kinetic coefficient of friction | 274 |
| VIII.C.5.        | Effect of slope                                              | 274 |
| VIII.C.6.        | Effect of reaction time                                      | 275 |
| VIII.C.7.        | Effect of tire selection                                     | 275 |
| VIII.C.8.        | Effects of anti-lock brakes                                  | 275 |
| VIII.D.          | Conclusions                                                  | 275 |
| VIII.D.1.        | Stopping distance                                            | 275 |
| VIII.D.2.        | Field-of-view limitations                                    | 276 |
| VIII.D.3.        | Average range ratio                                          | 276 |
| VIII.D.4.        | Overall conclusions                                          | 277 |
| Chapter IX.      | Computing hardware and equipment                             | 280 |
| IX.A.            | Discussion                                                   | 280 |
| IX.B.            | Analysis                                                     | 280 |
| IX.C.            | Results                                                      | 286 |
| IX.D.            | Conclusions                                                  | 286 |

|                                                                   |     |
|-------------------------------------------------------------------|-----|
| Chapter X. Prior experience and corporate or academic sponsorship | 288 |
| X.A. Discussion                                                   | 288 |
| X.B. Analysis                                                     | 288 |
| X.C. Results                                                      | 293 |
| X.C.1. Experience                                                 | 293 |
| X.C.2. Corporate sponsorship                                      | 294 |
| X.C.3. Academic sponsorship                                       | 295 |
| X.D. Conclusions                                                  | 295 |
| X.D.1. The effect of experience                                   | 295 |
| X.D.2. The effect of sponsorship                                  | 297 |
| X.D.3. Overall conclusions                                        | 299 |
| Chapter XI. Pre-mapping                                           | 300 |
| XI.A. Discussion                                                  | 300 |
| XI.B. Analysis                                                    | 300 |
| XI.C. Results                                                     | 302 |
| XI.D. Conclusions                                                 | 303 |
| XI.D.1. Terrain features indicative of the presence of water      | 304 |
| XI.D.2. Significant changes in elevation                          | 305 |
| XI.D.3. External map data                                         | 306 |
| Chapter XII. Path editing                                         | 307 |
| XII.A. Discussion                                                 | 307 |
| XII.B. Analysis                                                   | 307 |
| XII.C. Results                                                    | 309 |
| XII.D. Conclusions                                                | 309 |
| Chapter XIII. Failure analysis                                    | 311 |
| XIII.A. Discussion                                                | 311 |
| XIII.B. Analysis                                                  | 312 |
| XIII.B.1. Team 2005-02                                            | 313 |
| XIII.B.2. Team 2005-04                                            | 314 |
| XIII.B.3. Team 2005-05                                            | 314 |
| XIII.B.4. Team 2005-06                                            | 315 |
| XIII.B.5. Team 2005-09                                            | 315 |
| XIII.B.6. Team 2005-12                                            | 316 |
| XIII.B.7. Teams 2005-13 and 2005-14                               | 316 |
| XIII.B.8. Team 2005-15                                            | 317 |
| XIII.B.9. Team 2005-16                                            | 317 |
| XIII.B.10. Team 2005-17                                           | 318 |
| XIII.B.11. Team 2005-18                                           | 319 |
| XIII.B.12. Team 2005-19                                           | 319 |
| XIII.B.13. Team 2005-21                                           | 319 |
| XIII.B.14. Teams 2005-22 and 2005-23                              | 320 |
| XIII.C. Results                                                   | 320 |
| XIII.D. Conclusions                                               | 320 |

|                                                                                                                            |     |
|----------------------------------------------------------------------------------------------------------------------------|-----|
| Chapter XIV. System integration was the fundamental problem of the Grand Challenge                                         | 321 |
| XIV.A. Identify the fundamental problem of the Grand Challenge                                                             | 321 |
| XIV.A.1. Purpose-built vehicles                                                                                            | 322 |
| XIV.A.1.a. 2004                                                                                                            | 322 |
| XIV.A.1.b. 2005                                                                                                            | 322 |
| XIV.A.1.c. Conclusions                                                                                                     | 323 |
| XIV.A.2. Proprietary sensors                                                                                               | 324 |
| XIV.A.3. Navigation sensor integration                                                                                     | 326 |
| XIV.A.4. Pre-mapping                                                                                                       | 326 |
| XIV.A.5. Team 2004-03 self-stabilizing motorcycle                                                                          | 327 |
| XIV.A.6. Team 2004-21 programming language, compact “standard and solar charging system”, and “hybrid navigational system” | 327 |
| XIV.B. Reduce complexity                                                                                                   | 328 |
| XIV.B.1. Reduce the number of components                                                                                   | 328 |
| XIV.B.1.a. Eliminate unnecessary state sensors                                                                             | 328 |
| XIV.B.1.a.i. Fuel level monitoring sensors                                                                                 | 329 |
| XIV.B.1.a.i.a. 2004                                                                                                        | 329 |
| XIV.B.1.a.i.b. 2005                                                                                                        | 330 |
| XIV.B.1.a.ii. Temperature monitoring sensors                                                                               | 331 |
| XIV.B.1.a.ii.a. 2004                                                                                                       | 331 |
| XIV.B.1.a.ii.b. 2005                                                                                                       | 331 |
| XIV.B.1.a.iii. Results                                                                                                     | 332 |
| XIV.B.1.a.iv. Conclusions                                                                                                  | 333 |
| XIV.B.1.b. Leverage the capabilities of the challenge vehicle platform                                                     | 336 |
| XIV.B.1.b.i. Electrical power generation strategies                                                                        | 336 |
| XIV.B.1.b.ii. Computing hardware cooling strategies                                                                        | 338 |
| XIV.B.1.b.iii. Suspension                                                                                                  | 343 |
| XIV.B.1.c. Reduce the number of obstacle and path detection sensors in use by eliminating other sensors                    | 344 |
| XIV.B.2. Leverage existing COTS components                                                                                 | 345 |
| XIV.B.2.a. Challenge vehicle controls                                                                                      | 345 |
| XIV.B.2.b. Navigation sensor integration                                                                                   | 350 |
| XIV.B.2.c. High-quality sensors                                                                                            | 350 |
| XIV.B.3. Object classification or identification                                                                           | 350 |
| XIV.B.4. Miscellaneous observations                                                                                        | 351 |
| XIV.C. Reliability and redundancy                                                                                          | 353 |
| XIV.C.1. Select reliable components                                                                                        | 353 |
| XIV.C.2. Increase redundancy in key components                                                                             | 355 |
| XIV.C.3. Take proactive measures to ensure reliability                                                                     | 357 |
| XIV.C.4. Miscellaneous observations                                                                                        | 362 |
| XIV.D. Test and evaluation                                                                                                 | 362 |
| XIV.D.1. Perform adequate test and evaluation                                                                              | 362 |
| XIV.D.2. Use robust software development methodologies                                                                     | 374 |

|              |                                                               |     |
|--------------|---------------------------------------------------------------|-----|
| XIV.D.3.     | Simulate sensor noise and sensor failure                      | 377 |
| XIV.D.3.a.   | Noise                                                         | 377 |
| XIV.D.3.b.   | GPS “jump” and position error                                 | 378 |
| XIV.D.3.c.   | Other sensor failure                                          | 380 |
| XIV.D.4.     | Develop tools to analyze the results of test and evaluation   | 381 |
| Chapter XV.  | Potentially disruptive teams                                  | 383 |
| XV.A.        | Definition of “potentially disruptive team”                   | 383 |
| XV.B.        | Introduction                                                  | 383 |
| XV.C.        | Key factors                                                   | 384 |
| XV.C.1.      | Key factors contributed by DARPA                              | 384 |
| XV.C.2.      | Key factors identified through review of the published record | 385 |
| XV.D.        | What prevented potentially disruptive teams from succeeding?  | 387 |
| XV.D.1.      | Team 2004-02 / 2005-01                                        | 387 |
| XV.D.2.      | Team 2004-07 / 2005-05                                        | 392 |
| XV.D.3.      | Team 2005-06                                                  | 396 |
| XV.D.4.      | Team 2005-12                                                  | 401 |
| XV.D.5.      | Team 2004-16 / 2005-17                                        | 406 |
| XV.D.6.      | Team 2004-17 / 2005-18                                        | 411 |
| XV.E.        | Results                                                       | 414 |
| XV.F.        | Conclusions                                                   | 415 |
| Chapter XVI. | Research Methodology                                          | 419 |
| Appendix A:  | RDDF Analysis Application                                     | 563 |
| Appendix B:  | Vincenty's Inverse Solution                                   | 575 |
| Appendix C:  | DARPA Grand Challenge 2004 and 2005 Timeline                  | 578 |
| I.           | DARPA Grand Challenge 2004 and 2005 timeline                  | 579 |
| I.A.         | 2004 GCE                                                      | 579 |
| I.A.1.       | February 22, 2003                                             | 579 |
| I.A.2.       | April 1, 2003                                                 | 579 |
| I.A.3.       | June 18, 2003                                                 | 580 |
| I.A.4.       | October 14, 2003                                              | 580 |
| I.A.5.       | November 5, 2003                                              | 580 |
| I.A.6.       | November 26, 2003                                             | 581 |
| I.A.7.       | December 19, 2003                                             | 581 |
| I.A.8.       | December, 2003 or January, 2004                               | 581 |
| I.A.9.       | January 5, 2004                                               | 582 |
| I.A.10.      | March 8 - 12, 2004                                            | 582 |
| I.A.11.      | March 13, 2004                                                | 583 |
| I.B.         | 2005 GCE                                                      | 583 |
| I.B.1.       | June 8, 2004                                                  | 583 |
| I.B.2.       | August 14, 2004                                               | 583 |
| I.B.3.       | October 8, 2004                                               | 583 |
| I.B.4.       | February 11, 2005                                             | 584 |
| I.B.5.       | March 11, 2005                                                | 584 |
| I.B.6.       | April 4, 2005                                                 | 584 |

|         |                                |     |
|---------|--------------------------------|-----|
| I.B.7.  | May 2 - 15, 2005               | 584 |
| I.B.8.  | June 1, 2005                   | 584 |
| I.B.9.  | August 15, 2005                | 584 |
| I.B.10. | September 27 - October 6, 2005 | 584 |
| I.B.11. | October 8, 2005                | 584 |
| II.     | Timeframes and observations    | 585 |
| II.A.   | 2004 GCE                       | 585 |
| II.B.   | 2005 GCE                       | 585 |